



This shows the basement insulation process that was typical throughout the entire house at 26 Madbury Road before the wallboard and such went up.



Jan. 4, 2010

These pictures show how much MORE INSULATION the house has and tighter, warmer and better it will be. There is about 3 more inches of insulation on the inside walls from where the old walls were with its horsehair plaster and such.

The old wall is sandwiched around insulation at this window in the Chapter Room



Old Wall

New Wall