



Framing looking into the Dining Room and into the kitchen area (right)



TOP PHOTO:  
Looking into the corner of the  
Gerald Cormier Memorial Kitchen.

BOTTOM RIGHT: A view towards the rear of  
the old walk-in, kitchen and back pantry way.



Some may recall stairs here that went  
downstairs. They're gone and boarded  
up and the floor no longer sags.



The view from the houseparents' room (old president's room) looking into the chapter room.

**BOTTOM LEFT:**

The view from the houseparents' room toward the main hallway and back door. Sunlight is coming from the backdoor area.



Back area door is here



The new women's bathroom that is also wider and now handicapped accessible, still located on the first floor in the main hallway across the main stairwell.



The front hallway and front stairwell all frame out.



### Framing in the Chapter Room

Top: Looking into the old Ace and President's Room area - now for houseparents.

TOP RIGHT: The area where a window has plywood is where the handicapped accessible ramp will be leaving from and wrapping around the building.

### BOTTOM RIGHT:

The framing of the Chapter Room while looking out the front of the house.





This is pointed out because the workers on the project showed me that “no one makes cuts like this these days” and that’s with power tools. No one can imagine how difficult it was to make cuts like this, all throughout the house, 80-plus years ago - most likely by hand - and not the power tools of today.

This is in the Chapter Room on the first floor.