



The Cleaned out, cleaned up area of the old Boiler Room down in the basement.





Looking into the old party room where the bar, walk-in and fireplace used to be.



Looking through framing where the old walk-in, bar and shower room used to be.



Framing begins in old party room




Framing begins in old bar looking to where the showers, and walkin used to be.



Cleaning up the old shower room and walk-in area for framing and windows

A look under the stairs from the shower area, lower left.



Some parts are supported and made new after 80-plus years at 26 Madbury Road.

New basement windows, framing in old party room



Windows in the back of where the old shower room and walk-in used to be.