

12-04-09: Sheet rocking



Interior of the new south stairwell. If you look carefully at the print on the bottom of shot and perhaps stand on your head, you'll be able to see that the hallway sheetrock is 'hi-abuse', not that any of our new guys will ever try to put a fist through it. It's 5/8" thick, which will break a hand instead of buckling under a punch.



2<sup>nd</sup> Floor Hallway



Boiler Room -

